

HID® FARGO® INK1000

Printer Driver

Release Notes

Version: 2.0.0.7
PLT-05471, A.3
December 2022



Copyright

© 2022 HID Global Corporation/ASSA ABLOY AB. All rights reserved.

This document may not be reproduced, disseminated or republished in any form without the prior written permission of HID Global Corporation.

Trademarks

HID GLOBAL, HID, the HID Brick logo, the Chain Design, and FARGO are trademarks or registered trademarks of HID Global, ASSA ABLOY AB, or its affiliate(s) in the US and other countries and may not be used without permission. All other trademarks, service marks, and product or service names are trademarks or registered trademarks of their respective owners.

Contacts

For technical support, please visit: <https://support.hidglobal.com>.

What's new

Date	Description	Revision
December 2022	Release notes for printer driver 2.0.0.7.	A.3
February 2022	Release notes for printer driver 2.0.0.4.	A.2
September 2021	Release notes for printer driver 2.0.0.1.	A.1
October 2020	Initial release.	A.0

A complete list of revisions is available in [Revision history](#).

1.1 Scope

This document provides information on HID® FARGO® INK1000 Printer Driver version 2.0.0.7. This version can be utilized on the following operating systems:

- Windows 7 (32- and 64-bit)
- Windows 10 (32- and 64-bit)
- Windows 11 (64-bit)
- Windows Server 2012 R2 (64-bit)
- Windows Server 2016 (64-bit)
- Windows Server 2019 (64-bit)
- Windows Server 2022 (64-bit)

Note:

- The reference numbers associated with these features, issues, and fixes are from internal HID Global tracking systems.
- This version of the INK1000 printer driver requires version 2.0.1 or greater of the INK1000 printer firmware. The latest version of this printer firmware can be downloaded from [HID Drivers & Downloads](#).

1.2 Resolved issues

- Resolved an issue with the Japanese driver language (TTP-13314)
- Resolved an issue to allow Japanese captions to fit in the allotted space -GUI size (TTP-13314)

1.3 Known issues

- When batch printing, the HID Printer Status Monitor may not always display the active jobs accurately. (EINSTEIN-91)
- The event log in the HID Printer Status Monitor may not always display the job ID accurately. (EINSTEIN-196)
- In the **Printing Preferences**, you may be prompted to save your changes when closing the window, even after modifications have been made and saved. (EINSTEIN-214)
- When the INK1000 printer experiences an unable to feed condition, the HID Printer Status Monitor displays a warning icon instead of an error icon. (EINSTEIN-218)
- Audible alerts from the HID Printer Status Monitor occur only if the **Alert Options for Desktop Message** and **Icon Alert** are both on. (EINSTEIN-264)
- In the **Printing Preferences**, you may be prompted to save your changes when closing the window, even when modifications have not been made. (EINSTEIN-284)
- The **Printing Preferences** may display (Not Responding) in the title bar during the recalculation routine within the Ink Estimator. (EINSTEIN-286)
- When uninstalling the printer driver on Windows Server 2012, you may encounter a "driver in use" message. (EINSTEIN-309)
- Some users have reported that Windows Explorer is asking if they want to close the application because it is unresponsive after accessing the **Advanced** tab in **Printing Preferences**. (EINSTEIN-321)
- When the **Premium mode** is being used to print, darker gradients can sometimes show faint lines on the printed cards. (EINSTEIN-329)
- The Japanese version of the **Advanced** tab of the **Printer Preferences** displays some of the information incorrectly. (EINSTEIN-337)

Revision history

Date	Description	Revision
December 2022	Release notes for printer driver 2.0.0.7.	A.3
February 2022	Release notes for printer driver 2.0.0.4.	A.2
September 2021	Release notes for printer driver 2.0.0.1.	A.1
October 2020	Initial release.	A.0



hidglobal.com

For technical support, please visit: <https://support.hidglobal.com>

© 2022 HID Global Corporation/ASSA ABLOY AB.

All rights reserved.

PLT-05471, Rev. A.3

Part of ASSA ABLOY